



Connectors

Copper Inline Parallel & Butt



Parallels

#10.....	CPAR10
#8	CPAR 8
#6.....	CPAR 6
#4.....	CPAR 4
#2.....	CPAR 2
#1.....	CPAR 1
#1/0.....	CPAR 1/0

Butts

#10/12.....	CBUTT10
#8.....	CBUTT 8
#6.....	CBUTT 6
#6 Long.....	CBUTT 6L
#4.....	CBUTT 4
#4 Long.....	CBUTT 4L
#2.....	CBUTT 2
#2 Long.....	CBUTT 2L
#1.....	CBUTT 1
#1 Long.....	CBUTT 1L
#1/0.....	CBUTT 1/0
#1/0 Long.....	CBUTT 1/0L
#2/0.....	CBUTT 2/0
#2/0 Long.....	CBUTT 2/0L
#3/0.....	CBUTT 3/0
#3/0 Long.....	CBUTT 3/0L
#4/0.....	CBUTT 4/0
#4/0 Long.....	CBUTT 4/0L
#250-MCM.....	CBUTT250MCM



